## REMOVAL ASSESSMENT AND SITE INITIALIZATION



DATE SUBMITTED (Red) FOR EPA ID #: 81/9191

## Removal Site Assessment (If applicable)

Removal: Removal Tracking Generic Events:  Removal Assessment (YA) - Non NPL Removal Investigations (RS) - NPL  Contact Name (OSC): Sten famile  d Mennes Matthe	Removal Certification (XC)  OSC Name: Date Form Received from OSC:/_/
Lead: F Actual Start Date: 81619/	Actual Complete Date://
Pre-Remedial Assessment Info. Entered By:	Date:
	PA-2944
Site Initialization Site Name: SUN BAPANY CHEMICAL I Street Address: 3301 HUNTING PARK	O. FIRE DADGEORGE
Site Name: OUN COMPANY CHEMICAL I	PAINT EPAID#: UNUTYOS) 170%
Street Address: 3301 HUNTING PARIS	WasteLAN ID:#:4479
	Data
City: Phila ID State: PA	Zip Code: 19139
, ,	
(Choose one in each of the following categories:)	
Owner Indicator: — (ST) State Federal — (CO) County — (PR) Privately Owned — (MN ) Municipality	deral Facility Indicator:(Y) Yes(N) No(OH) Other
Category:  (A) (Abandoned) ——  (B) (Chemical Plant) ——  (G) (Groundwater) ——  (H) (Housing Area) ——	(I) Industrial Waste Treatment (L) Landfill (M) Manufacturing Plant (O) Other (Specify:)
(F) NPL Site	ident Type: Blank (O) Oil Spill (N) Non-Oil Spill
Site Class: (F) Fund Lead (N) (FE) Federal Enforcement (S)	ND) No Determination SE) State Enforcement

	Discovery (Red)
Lead: (F) Fund Financed (S) State	Discovery Date: 8,5,91.  Agency: Thila Ture height
Reported By: Dispatcher # 6	6104 Phone: (2/5) 592- 5987
	Referral  Some Enter Date: 815191
RPM/OSC Name: Stew Sarvela Other Regional Contact: Stanis	105C Phone: 62/5) 597-7.  Phone: 62/5) 597-81;
Site Description: ID: OSC C	lled to assess structure fire
which stored paint production dried Llun	buils he resurs. Factily in Storage areas freated
outside hurning stru	uture.
Site Directions 110	
wover. mat'ls stored TH: air monetown of	ly print of end pegments and in fiber fores or drums. Serformed which deleted usual sevidince of hogardone
fire by- products in	Sevidence of hozardone
Comments: Napar myras  AT: a survey of the	area will be performed to goldon materials here being
redeased. PADENTS over	see leany operations by
the responsible par	M.
	1/2 x/a0/91
	Inst Lanua

To: ERD/OERR (EPA5511)
To: D.MATLOCK (EPA93057)

To: REGION03.TAT (EPA9322)

To: RRC (EPA9374)

From: REGION03.TAT (EPA9322) Delivered: Tue 6-Aug-91 (Red) 07 EDT Sys 163 (98)

15:07 EDT Sys 163 (98)

Subject: SUN CHEMICAL COMPANY PAINT FIRE POLREP #1

Mail Id: IPM-163-910806-136060616

POLREP #1 SUN COMPANY CHEMICAL PAINT FIRE 3301 HUNTING PARK AVE. PHILA., PHILA. COUNTY, PA 19129 ATTN: GREGG CRYSTALL AND STEPHEN LUFTIG

- SITUATION (0230 HOURS, TUESDAY, AUGUST 6, 1991)
  - A. AT APPROXIMATELY 2100 HOURS 8/5/91, THE PHILA. FIRE DEPT. (PFD) RESPONDED TO A STRUCTURE FIRE AT THE SUN CHEMICAL PLANT LOCATED AT THE ABOVE ADDRESS. WAS CONFINED TO ONE STRUCTURE, WHICH STORED PRIMARILY PAINT PRODUCTS AND RESINS. DUE TO THE POSSIBILITY OF HAZARDOUS MATERIALS AT THE SCENE, THE FIRE DEPT. HAZ-MAT ADMINISTRATIVE UNIT (PFD-HMAU) ALSO RESPONDED.
  - B. DUE TO THE POSSIBILITY OF HAZARDOUS MATERIALS ENTERING THE AIR OR WATER, OTHER AGENCIES WERE REQUESTED TO RESPOND, INCLUDING PHILA. WATER DEPT., PHILA. AIR MGMT., PA DER, AND EPA.
  - C. THIS FACILITY IS LOCATED IN A PRIMARILY INDUSTRIAL AREA. LOCAL OFFICIALS PROVIDED SECURITY AND REDIRECTED TRAFFIC AT THE SCENE. AN APPROXIMATE 12 BLOCK AREA WAS RESTRICTED FOR EMERGENCY PERSONNEL.
  - D. THE CAUSE OF THE FIRE IS NOT KNOWN AT THIS TIME. NO PERSONNEL ON SCENE RECEIVED ANY CHEMICAL EXPOSURES DUE TO THE BLAZE. SUN COMPANY PERSONNEL WERE ON SCENE TO ASSIST RESPONDERS.

## II. ACTIONS TAKEN

A. AT APPROXIMATELY 2230 HOURS, EPA RRC DUTY OFFICER FOX CONTACTED OSCs JARVELA, MATLOCK, AND TAT. THESE PERSONNEL MET ON SCENE AT 2330 HOURS TO PROVIDE TECHNICAL ASSISTANCE AND COORDINATE WITH LOCAL OFFICIALS AT THE SCENE.

- B. SUN COMPANY PERSONNEL USED WORKER HEALTH AND SAFETY INFORMATION TO IDENTIFY THE MATERIALS STORED IN THE BUILDING WHERE THE FIRE WAS LOCATED. THESE MATERIALS WERE PRIMARILY PAINT AND INK PIGMENTS AND WAXES. PRODUCT INFORMATION WAS PROVIDED AT THE SCENE BY COMPANY PERSONNEL. SEVERAL DRUM STORAGE AREAS WERE LOCATED OUTSIDE OF THE BURNING STRUCTURE. PFD MAINTAINED STREAMS OF WATER ON THESE CONTAINERS TO PREVENT THEM FROM BECOMING INVOLVED IN THE FIRE.
- C. AIR MONITORING WAS PERFORMED DOWNWIND OF THE FIRE BY TAT.
  USUAL FIRE BY-PRODUCTS WERE DETECTED; HOWEVER, NO
  EVIDENCE OF HAZARDOUS VAPOR MIGRATION COULD BE FOUND.
  ALTHOUGH SOME VOLATILE MATERIALS WERE INCLUDED IN THE
  INVENTORY, SITE PERSONNEL INFERRED THAT THESE MATERIALS
  WOULD BE THE FIRST TO BE RELEASED IN A FIRE SITUATION,
  AND IT WAS LIKELY THAT ANY SUCH VAPORS WOULD HAVE
  DISSIPATED IN THIS TIME FRAME.
- D. PHILA. WATER DEPT. AND PA DER MONITORED THE OUTFALLS FROM THE FACILITY LEADING TO THE SCHUYLKILL RIVER. COMPANY PERSONNEL INFORMED OSC JARVELA THAT ALL WASTEWATER IS AUTOMATICALLY DIVERTED TO A WASTEWATER TREATMENT SYSTEM.
- E. AIR SAMPLING WAS DISCUSSED AMONG THE AGENCIES PRESENT.
  OSC JARVELA RECOMMENDED AIR SAMPLING BE WITHHELD AT
  LEAST UNTIL ALL MATERIALS STORED IN THE BUILDING WERE
  IDENTIFIED. ALSO, SINCE THE FIRE WAS STILL IN PROGRESS,
  FIRE BY-PRODUCTS MAY MASK ANY SIGNIFICANT FINDINGS.
  ALSO, AIR SAMPLING WOULD NOT PROVIDE REAL TIME DATA TO
  THE RESPONDERS AND WOULD NOT BE REPRESENTATIVE OF THE
  HAZARDS ONCE THE FIRE WAS EXTINGUISHED.
- F. TAT REVIEWED PRODUCT INFORMATION PROVIDED BY SUN COMPANY REPRESENTATIVES. EPA RECOMMENDED THAT PERSONNEL ATTACKING THE FIRE OR WORKING IN THE DIRECT AREA OF THE FIRE WEAR RESPIRATORY PROTECTION TO PREVENT THE INHALATION OF METAL DUSTS.
- G. MOST OF THE MATERIALS CONTAINED IN THE BUILDING WERE STORED IN FIBER BOXES OR DRUMS. THERE WAS NO DOCUMENTATION BY THE PFD OF PROPELLING OR PRESSURIZED DRUMS OR CONTAINERS. SEVERAL CLOUDS OF COLORED SMOKE, RESULTING FROM THE BURNING PAINT PIGMENTS, WERE



OBSERVED. SITE PERSONNEL WERE RECOMMENDED TO DECON THOROUGHLY WITH SOAP AND WATER.

- H. REPRESENTATIVES AT THE SCENE EXPRESSED CONCERN OF THE EFFECT OF THE FIRE ON A DAY CARE CENTER LOCATED NEARBY. ALL AGENCIES AGREED RECOMMENDATIONS WOULD BE MADE LATER IN THE MORNING ONCE THE STATUS OF THE FIRE COULD BE DETERMINED.
- I. AT 0200 THIS DATE, PFD-HMAU JANDA DECLARED THE FIRE TO BE UNDER CONTROL. FURTHER OPERATIONS WOULD BE DIRECTED UNDER THE COORDINATION OF THE FIRE OFFICIAL AT THE SCENE.

## III. FUTURE PLANS

- A. EPA, TAT, AND PFD FIRE MARSHALL'S OFFICE TO MEET ON SCENE AT 0900 HOURS. A SURVEY OF THE AREA WILL BE PERFORMED TO DETERMINE IF ANY HAZARDOUS MATERIALS ARE BEING RELEASED WHICH MAY POSE AN IMMINENT THREAT TO PUBLIC HEALTH OR THE ENVIRONMENT.
- B. EPA TO CONTINUE TO COORDINATE WITH STATE AND LOCAL OFFICIALS.
  A REPRESENTATIVE FROM OFFICE OF PUBLIC AFFAIRS WILL BE REQUESTED TO ASSIST ON SCENE 8/6/91.
- C. PA DER TO OVERSEE CLEANUP OPERATIONS BY THE RESPONSIBLE PARTY.

STEPHEN D. JARVELA, OSC EPA REGION III PHILA., PA DENNIS MATLOCK, OSC EPA REGION III PHILA., PA

REGION III INCIDENT NOTIFICATION REPORT 1.Case No.: 8-5-9 2. Reported: (mm/dd/yy) 3. Time: Recorded By: Through NRC: 5. NRC Case No.: DISPATCHER 6104 6. Reported By: # 7. Organization Name: FIRE PHILADELPHIA REPORTER DEPT 11. state 12. local 9. discharger 10. public 8. Organization: 13 lederal 14. Address: 15. City: 16. County: 18. Zip 59E7 19. Phone: As Above in A if 9 applies 21. Name: 23. City County 26. Zip: 27. Phone: ( NCIDENT SUN CHEMICAL CO. As Above in B 29. Street or Approx. Location: LOCA. VE 344 and TNDIANA HUNTING PARK 30. City: ADELIPHIA PA 31. County:  $\Box \Box \leftarrow \vdash \Box$ 33.Spill Date: (mm/dd/yy) 34. Spilt Time: other Material UN/ Quantity CHRIS Units Material: CAS No. Unknown DOT No Spilled E. MATERIAL hazardous substance Code (Circle 1) lb. gal. 41. bbl. oth 38. lb. g.il. 47 bbl. otn UNK-nOWNS DRUMS 1.4 Source of Spill: 60. offshore SOURCE 54. highway 56. railway 58. fixed facility 61. Vehicle ID or Carrier No. 55. air transport 57. vessel 59. pipeline Unknown 62. Description: Medium Affected: 63. air 64. land 65. water ☐ 66. groundwater 67. within facility only G. MED. drinking water none 68. Waterway Affected H. CAUSE Reported Cause: 69. transportation accident 75. other 71 operational error 73. dumping 70. equipment failure 74. unknown 72. natural phenomenon 76 Description: 77. no. of injuries 78. no of deaths - O 4 Z Damages: 79. property damage > \$50,000 J. ACT. IONS Evacuation 81. Response Action Taken: UNKNOTUN K. NOTI. FIED 82. state/local Caller Has Notified: 83. discharger 84. USCG 85. other 86. unknown Agency Name L. COM-MENTS LARM FIRE 87. Comments Additional Information Responsibility: Non-duty hours CWA 308 Spill letter 1 000/EPA Response by: responsible party other USCG REGIONAL DATA FIELDS Agency Name: If OSC: Name CERCLA Activation 311 Activation -- PIC # usca: WFO: **EPA** NOTIFICATION: EPA: ZOIS State/local: Name, date, & time; OSC notified: JARVELA - MATLICIE Referral:

.